

Letter	Revision	Date	Date	Date	Checked	Date	Approved	Date	Scale
A	Remove Bombball Cap from Black wires and fit an Eyelet instead so as to make it an Earthing point.	Modified 17/12/04 C.J.B.							Scale NTS
B	Put in Extra wiring for Hood Release Motors.	Modified 13/01/05 C.J.B.							

